### Article 15 – Capital Budget Requests Admin

Hybrid SUV

# DPW Hybrid SUV (Replace 2010 Escape) - \$35,000






### DPW Hybrid SUV (Replace 2010 Escape) - \$35,000

- •Current vehicle is used by the Business Manager, Engineering, and Water and Sewer Superintendent
- •Vehicle is nearing the end of its useful life, heavily rusted, uptick in maintenance
- Price based on State Bid for similar vehicles

## Article 15 – Capital Budget Requests Highway

- Sandy Pond Road Sidewalk Design
- Highway Garage Roof Repair

#### Sandy Pond Road Sidewalk Design



#### Sandy Pond Road Sidewalk Design

- Design of a sidewalk from Snake Hill Road to Westford Road.
- •Project is identified in Town's Complete Streets Prioritization Plan. DPW has also received several requests for a sidewalk in this location.
- •Funding request will provide preliminary design and cost estimate for the project. The construction would likely be completed separately by submission for Complete Streets Grant funding and/or other available grants.
- Design will consider:
  - Property/ROW impacts
  - Environmental Permitting
  - Design Criteria (sidewalk vs multiuse path)



#### Highway Garage Roof Repair

- •Highway garage roof is in poor condition, assessment:
  - Leaks
  - EPDM membrane tearing/failing due to age and UV exposure
  - Failure of termination bars and rotted wood blocking
  - · Saturated, failed insulation
- Failing conditions are a potential safety and structural hazard
- •\$20k repairs based on quotes to extend the life 10-years



### Highway Garage Roof Repair



EPDM membrane hanging off perimeter.



Termination bar/perimeter failure.



fasteners are pulling out of the rotted wood blocking, likely due to lack of a proper drip edge and water infiltrating the assembly. The EPDM membrane is also shrinking an d tearing from UV exposure.



### Article 15 – Capital Budget Requests Stormwater

Biofiltration/Outfall Improvements

#### Biofiltration/Outfall Improvements

#### **Stormwater Quality Improvements:**

- •Meets water quality improvements of MS4 Permit and recommendations in the "2016 Biological, Survey, Assessment and Management Recommendations for Ayer's Ponds" by Geosyntec.
- •Reduce pollutant loading to Ponds, especially phosphorus.
- •This Spring improvements to outfall on Groton Harvard Road and rain garden installation on Oak Ridge Drive.

